



CI 4
60x110
CT=-0.15
CF=-1.45
Prof.=1.30

CI 3
60x110
CT=-0.15
CF=-1.80
Prof.=1.65

CI 1
60x110
CT=-0.15
CZe1=-1.12
CZe2=-1.95
CZs=-1.80

CI 2
60x60
CT=-0.15
CZe=-0.85
CZs=-0.87

PVC Ø160
p=1%



